


CORNER RECORD

Document Number 2562-B

City of Stevinson County of Merced, California

Brief Legal Description Point on east/west quarter-section line at intersection of west sideline of Lander Ave. per 11 RS 8, MCR.



S10, T7S, R10E MDM

CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey May 19, 2014

COORDINATES (Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 3/4" Iron Pipe; no tag, down 0.11',  
Boundary Corner; point on east/west quarter-section line at the west sideline of Lander Ave. per  
11 RS 8, MCR.  
Set ties as depicted on the reverse page.

A description of the physical condition of the monument as found and as set or reset: Found 3/4" monument down 0.11',  
no tag.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with  
the Land Surveyor's Act on June 25, 2014  
Signed [Signature] P.L.S. or R.C.E. No. LS6646



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received June 25, 2014  
and examined and filed July 10, 2014  
Signed [Signature] P.L.S. or R.C.E. No. 4895  
Title County Surveyor



County Surveyor's Comment \_\_\_\_\_



NTS

ROW CROP

FD 1" IRON PIPE & PLUG,  
PUNCH ON E'LY RIM;  
FORMERLY CALTRANS  
CONTROL MONUMENT #108.

OPEN FIELD

DIRT ROAD

FD 3/4" IRON PIPE  
NO TAG, DOWN 0.11'

ALMONDS

SET  
PK NAIL WITH CALTRANS  
BRASS TAG STAMPED "A"  
SE'LY SIDE OF  
POWER POLE,  
No.3490

80.12'

51.43'

165

231.53'

SET  
PK NAIL WITH CALTRANS  
BRASS TAG ; SW'LY SIDE  
OF POWER POLE,  
No.3450

TO HILMAR

STATE ROUTE

TO LOS BANOS

2nd Ave.