

2632.

CO. ER RECORD

COUNTY OF Merced T. 9S R. 14E Mt. Diablo MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT 11-23- 19 77



Northwest corner of Lot 9, Block 23, (Section 23) as shown on the Map of the Bliss Ranch Subdivision on file in Volume 7 of Plats, at page 44, M.C.R.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 4" x 4" redwood 0.5 below asphalt road


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Found 4 x 4 redwood 0.5 below asphalt road.
 Set 1" O.D. pipe with plug marked L.S. 4156 in center of redwood.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 23.94 East from nail & shiner top of 4" x 4" fence post.
- 40.22 Northeast from "X" on South side of 36" standpipe.
- 68.18 Northeast from "X" on South side of 36" standpipe.



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
 ON Feb. 9 19 77
 SIGNED: John E. Davis
 L.S. ST. R.C.E. No.: 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____
 AND EXAMINED AND FILED _____ 19_____
 BY: _____
 TITLE: _____
 DOCUMENT No. 2632-C
 STATEMENT ON BACK OF SHEET
 YES NO