

2647C

CORNER RECORD

COUNTY OF MERCED T. 10 S. R. 12 E. M.D.B. & M. MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION - DATE OF VISIT 8-15 19 78



N 1/4 CORNER SECTION 11, T.10 S., R.12 E., M.D.B. & M.

HUTCHINS ROAD

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 3/4" IRON PIPE, TAGGED L.S. 2737 4" DOWN, ON SPLIT BETWEEN SECTION CORNERS: (2640.29' MEAS. E. & W.)

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 32.21 S.E. OF NAIL AND TIN JUNC. P.P.
- 88.66 S.W. " " " " P.P.
- 62.70 N.E. " " " " P.P.
- 14.4 W. " POLE LINE N.
- 26.7 S. " " " E. & W.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEBRUARY 5 19 79.

SIGNED: William D. Gentry

L.S. or R.S. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED _____ 19 _____.

BY: _____ TITLE: _____

DOCUMENT No. 2647C

STATEMENT ON BACK OF SHEET

YES NO