

#264

CORNER RECORD

COUNTY OF MERCED T. 10 S. R. 12 E. M.D.B. & M. MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION - DATE OF VISIT 8-15 1978



N.W. CORNER SECTION 2, T.10 S., R.12 E., M.D.B. & M.

ELGIN & HENRY MILLER ROADS

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 1 1/2" IRON PIPE 24" DOWN, WITH 3/4" BENT IRON PIPE INSIDE

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

REPLACED 3/4" IRON PIPE AND TAGGED L.S. 2737, 6" DOWN

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 41.08 S.W. OF NAIL & TIN
- 40.24 S.E. ✓ ✓ JUNC. P.P.
- 99.34 N.E. ✓ ✓ P.P.
- 28.8 S. ✓ POLE LINE W.
- 28.4 E. ✓ ✓ N-S.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEBRUARY 5 1979.

SIGNED: William O. Bentley
 L.S. or R.C.E. No.: 2737

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____
 AND EXAMINED AND FILED _____ 19____.

BY: _____
 TITLE: _____

DOCUMENT No. 2647

STATEMENT ON BACK OF SHEET

YES NO