


CORNER RECORD

Document Number 2776AA
County of Merced, California

Area City of Ingomar

Brief Legal Description Section 3, T. 9 S., R. 9 E. MDB&M



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey July 7, 2000

COORDINATES (Optional)

N. _____
E. _____
Zone NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial


Corner – Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
See sketch on reverse side.

A description of the physical condition of the monument as found and as set or reset: Established offset
location of the NE corner of Parcel 3; SE corner Parcel 2 and the SE corner of
Parcel 1 of Parcel Map Book 34, Page 17, Merced County Records.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Land Surveyor's Act on July 12, 2000
Signed Robert C. Hart, Jr. P.L.S. or ~~P.C.E.~~ No. 5784



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 7-15-00
and examined and filed 8-15-00
Signed Roy L. Turney P.L.S. or P.C.E. No. 5523
Title Dep. Co. Surv.



County Surveyor's Comment _____

