


CORNER RECORD

Agency Index 2845

Document Number _____

City of _____ County of MERCED, CaliforniaBrief Legal Description S.W. COR. SECTION 32 T.9S. R.11E. MDB&M.**CORNER TYPE****COORDINATES (Optional)**T.9S., R.11E.

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey MAY 21, 2019

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

 Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

 See sheet #2 for description(s):**MONUMENT MAY BE DISTURBED DUE TO CONSTRUCTION****SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on 6 Nov 2019Signed [Signature] P.L.S. or R.C.E. No. 9417**COUNTY SURVEYOR'S STATEMENT**This Corner Record was received DECEMBER 23, 2019and examined and filed JANUARY 3, 2020Signed [Signature] P.L.S. or R.C.E. No. 8664Title COUNTY SURVEYOR**County Surveyor's Comment**



SCALE: 1" = 30'

HENRY MILLER AVENUE

S.W. COR. SEC. 32
FOUND 2 1/2" IRON PIPE
NO TAG, IN MONUMENT WELL.

S.W. 1/4
SECTION 32
T.9S. R.11E.

N.W. 1/4
SECTION 5
T.10S. R.11E.

S.E. 1/4
SECTION 31
T.9S. R.11E.

N.E. 1/4
SECTION 6
T.10S. R.11E.

FOUND N&S IN ASPHALT

FOUND 80D NAIL

12.06'

63.82'

T.9S.
T.10S.

T.9S.
T.10S.

61.03'

FOUND N&S IN P.P.

141.01'

FOUND N&S IN P.P.

PP