


# CORNER RECORD

Document Number 2087-A

City of \_\_\_\_\_

County of MERCED, California

Brief Legal Description NORTH 1/4 CORNER SECTION 2, T. 11S, R. 12E, M.D.B. & M.



T11S, R12E

### CORNER TYPE

Government Corner  Control   
 Meander  Property   
 Rancho  Other   
 Date of Survey 10-30-2002

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ NAD27  NAD83   
 NAD83 Epoch \_\_\_\_\_  
 Elev. \_\_\_\_\_  
 Vert. Datum: NGVD29  NAVD88   
 Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
NORTH 1/4 CORNER SECTION 2, TOWNSHIP 11 SOUTH, RANGE 12 EAST, M.D.B. & M., ALSO CENTERLINE INTERSECTION OF EUCALYPTUS AVE. AND CENTER AVENUE, BOTH REESTABLISHED USING MERCED COUNTY CORNER RECORD No. 2087

A description of the physical condition of the monument as found and as set or reset: SET 3/4" IRON PIPE WITH L.S. 7621 TAG IN MONUMENT WELL IN BOTH LOCATIONS.


### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on DEC. 24, 2002  
 Signed David D. Heinrich P.L.S. or R.C.E. No. 7621



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JAN - 2003  
 and examined and filed JAN 24, 2003  
 Signed Roy L. Turney P.L.S. or R.C.E. No. 5523  
 Title Dep. Co. Surveyor



County Surveyor's Comment \_\_\_\_\_

