


NO. 64-A

### CORNER RECORD

COUNTY OF MERCED T. 8 S R. B E MDBEM MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER  MEANDER  RANCHO  CONTROL  OTHER

CORNER IDENTIFICATION — DATE OF VISIT 12/11 19 74



The southwest corner of lot 27 of the Realty Development Co's Subdivision of section 36, T.8S., R.8E.

CORNER — LEFT AS FOUND  FOUND AND TAGGED  REESTABLISHED OBLITERATED CORNER  REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

No existing corner was found and the location was established by proration between the southeast and southwest corners of said section 36 as shown on said subdivision.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

A 3/4" x 36" Iron Rod, Tagged R.C.E. 13760

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST  SECOND  THIRD   
STATIONS USED: NGS (USC & GS)  STATE  COUNTY  OTHER  STATION \_\_\_\_\_ STATION \_\_\_\_\_  
ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

(Fold)

SKETCH: (Include reference tie or witness points, remarks and topo of area) SEE MERCED Co. Rd Dept. Bk No. 709

SULLIVAN OUTSIDE CANAL

COTTONWOOD

RD. # 248

36 25'  
1" I.D. IRON PIPE  
ON SEC. LN  
1/4 COR. FOR SEC. SOUTH.

Shinner in P.P.

Shinner in Service Pole

SET 3/4" IRON ROD BY  
36" Long Tagged R.C.E.  
13760

CEMETARY

1/4 CORNER IS 1' EAST OF FENCE LINE SOUTH  
AND 29' SOUTH OF POWER POLE LINE EAST  
& west.

**SURVEYOR'S CERTIFICATE**

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON \_\_\_\_\_ 19 \_\_\_\_.

SIGNED: \_\_\_\_\_

L.S. or R.C.E. No.: \_\_\_\_\_

SEAL

**COUNTY SURVEYOR'S CERTIFICATE**

THE CORNER RECORD WAS RECEIVED \_\_\_\_\_ 19 \_\_\_\_

AND EXAMINED AND FILED \_\_\_\_\_ 19 \_\_\_\_

BY: \_\_\_\_\_

TITLE: \_\_\_\_\_

DOCUMENT No. 3064-A

STATEMENT ON BACK OF SHEET

YES  NO