

#3107A

CORNER RECORD

COUNTY OF Merced T. 9 S. R. 15 E. Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION -- DATE OF VISIT June 11, 19 80



Northeast corner of Southeast quarter of Southeast quarter, Section 4.

CORNER -- LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

2" O.D. pipe @ 0.6 feet below ground line. Corner was destroyed in canal construction.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

25 foot offset west. Set 1" O.D. pipe @ 0.4 feet below groundline tagged R.C.E. 12700.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 25 foot offset to West
- 93.47 Northwest from nail & shiner in power pole.
- 22.50 South from "X" on west side of 8" standpipe.
- 45.06 North from "X" on east side of 8" standpipe.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY MR. STANLEY UNDER THE DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 25 June 19 50

SIGNED: Frank C. Stambaugh No. 12700

State or R.C.E. No.: 12700



COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19 _____ AND EXAMINED AND FILED _____ 19 _____

BY: _____

TITLE: _____

DOCUMENT No. 3107A

STATEMENT ON BACK OF SHEET YES NO