

#315

COLLAR RECORD

COUNTY OF Merced T. 9 S. R. 14 E. Mt. Diablo MERIDIAN CALIFORNIA
CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT June 3, 1977



Northwest Corner of Lot 4, Block 23 (Section 23) as shown on the Map of the Bliss Ranch Subdivision on file in Volume 7 of plats at page 44, M.C.R.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


Found 1" O.D. iron pipe at 0.5 below road surface.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

19.40 Northwest from nail & shiner in power pole.
84.48 Northwest from nail & shiner in power pole.
25.35 Southeast from nail & shiner in power pole.
Set 2 foot shiners East & South.



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
January 31, 1979
SIGNED: *John J. Corner*
L.S. No. 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____
AND EXAMINED AND FILED _____ 19_____
BY: _____
TITLE: _____
DOCUMENT No. 3157
STATEMENT ON BACK OF SHEET

YES NO