

3158

CO. ER RECORD

COUNTY OF Merced T. 9 S R. 14 E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT April 20, 1976



Northwest Corner of Block 24 (Section 24) as shown on the Map of the Bliss Ranch Subdivision on file in Volume 7 of plats page 44, M.C.R.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 4" x 4" redwood 1.2 below road surface.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Found 4" x 4" redwood 1.2 below road surface.
Set 1" O.D. pipe with plug tagged L.S. 4156 in center of redwood at road surface.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 28.66 Northeast from nail & shiner in power pole.
- 30.44 Northwest from nail & shiner in railroad tie.
- 32.47 Southwest from nail & shiner in power pole.

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
ON VIS January 31, 1979

L.S. 4156

SIGNED

John E. Davis

L.S. or R.C.E. No.:

4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____

AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. 3158

STATEMENT ON BACK OF SHEET

YES NO