

3395

CORNER RECORD

COUNTY OF Merced T. 9 S R. 14 E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT December 6, 1976



Northwest Corner of Lot 4, Block 25 (Section 25) as shown on the Map of the Bliss Ranch Subdivision on file in Volume 7 of plats at page 48, M.C.R.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


Found 4" x 4" redwood with 60D nail in center.
Put plastic plug on nail marked L.S. 4156.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 52.29 North from nail & shiner on West side of power pole.
- 49.37 Northeast from nail & shiner in utility pole.
- 50.40 South from nail & shiner in 4" x 4" fence post.
- 56.20 Northeast from center of pump.



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 31, 1979
L.S. 4156
SIGNED: *Johnny E. Davis*
L.S. or R.C.E. No. 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19_____
AND EXAMINED AND FILED _____ 19_____
BY: _____
TITLE: _____

DOCUMENT No. 3395

STATEMENT ON BACK OF SHEET YES NO