

3400

COLLAR RECORD

COUNTY OF Merced T. 9 S R. 14 E Mt. Diablo MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION -- DATE OF VISIT April 20, 1976



Northwest Corner of Lot 20, Block 26 (Section 26) as shown on Map of the Bliss Ranch Subdivision on file in Volume 7 of plats, page 48, M.C.R.

CORNER -- LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


Found 1" O.D. pipe with plug L.S. 3733 at 0.2 below road surface.
(Found remains of redwood beside pipe)

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

35.42 North from nail & shiner in railroad tie.
13.28 South from nail & shiner in power pole.
27.56 Northwest from nail & shiner in 4" x 4" post.



SURVEYOR'S CERTIFICATE
JOHNNY E. DAVIS
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 31, 1979
L.S. No. 4156
SIGNED: *Johnny E. Davis*
L.S. or M.C.R. No.: 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19_____
AND EXAMINED AND FILED _____ 19_____
BY: _____
TITLE: _____
DOCUMENT No. 3400
STATEMENT ON BACK OF SHEET YES NO