


3424

CO' ER RECORD

COUNTY OF Merced T. 9 S R. 15 E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION -- DATE OF VISIT April 17, 19 75



West 1/4 corner Section 14, T 9 S., R 15 E.

CORNER -- LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


Found 5/8 rod 0.6 below road surface with 2" O.D. pipe at 30' Westerly.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION EASTINGS (X) STATION ZONE ELEVATION NORTHINGS (Y)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 30.46 East from nail & shiner in fence post.
36.06 Northeast from nail & shiner in power pole.
59.48 Southeast from mark in 8" x 6' standpipe.
30' East from 2" O.D. pipe.



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 29, 19 79.
SIGNED: [Signature]
L.S. No.: 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED AND EXAMINED AND FILED 19

BY:
TITLE:
DOCUMENT No. 3424

STATEMENT ON BACK OF SHEET

YES [] NO []