

#


426-B

CORNER RECORD

COUNTY OF Merced T 9S R 15E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [] MEANDER [] RANCHO [] CONTROL [] OTHER [X]

CORNER IDENTIFICATION - DATE OF VISIT 6-3-1977



Property corner @ 880.20 feet South of center 1/4 corner, Section 14, 9/15 as shown on Map of Sierra Vista Lands filed in Volume 8 of Maps at page 31, M.C.R.

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1-3/8" O.D. pipe @ 0.4 ft. below groundline


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____ ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

5.35 Northwest of nail & shiner in railroad tie fence post.

25.50 South of nail & shiner in corner railroad tie fence post.



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT

IS. 410N FEB. 9 1979

SIGNED: [Signature]

L.S. or R.C.E. No.: 4136

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. 3426-B

STATEMENT ON BACK OF SHEET

YES [] NO []