


# CORNER RECORD

Document Number 346

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description N.E. COR. Sec. 16, T. 10 S. R. 10 E.



### CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey \_\_\_\_\_
- Control
- Property
- Other

### COORDINATES (Optional)

N. \_\_\_\_\_  
 E. \_\_\_\_\_  
 Zone \_\_\_\_\_ Datum \_\_\_\_\_  
 Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

All records show 1" I.P.  
Monument well set over 1/2" rod (SEE REVERSE SIDE FOR SWING TIES)  
POINT TIED OUT PRIOR TO PAVING EFFORT BY MERCED COUNTY.  
MONUMENT WELL SET AFTER PAVING

A description of the physical condition of the monument as found and as set or reset: THESE TIES ARE

FOR THE PURPOSE OF PERPETUATING THE FOUND MONUMENTATION. NO  
CLAIM IS MADE TO THE RELATIONSHIP OF THE POINTS OR LINES SHOWN  
HEREON TO THE TRUE BOUNDARY

### SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JANUARY 1997.


Signed Roy L. Turney L.S. or R.C.E. Number 5523



### COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 1997 and examined and filed JANUARY 16 1997.

Signed Roy L. Turney Title DEP CO. SUR



County Surveyor's Comment \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_  
 \_\_\_\_\_

T.I.D.S. R.I.I.E.

ROAD

DELTA

NAIL & SHINER IN POWER POLE

SEC. 9

SEC. 10

Monument Well Set over 1/2" REBAR

FD. 1/2" REBAR W/TAG UNREADABLE SEC. COR. Rebar 0.6 Below Surface

SET NAIL & SHINER IN 1'x2" ON TOP OF BANIK

DRAIN DITCH

DIRT DRIVE

NAIL & SHINER IN TOP FENCE POST

120.02'

93.35'

67.12'

SEC 16

SEC. 15