
CORNER RECORD

Document Number 3718 - 646

City of DELLA			Co	unty of	MERCE	:D		, California
Brief Legal Descrip	TION CENTERLINE INTER AND ORCHARD C	r Section	1 CA	امحاد	WENT.	at schei	YDEL	AUE.
	CORI	VER TYPE			COOR	DINATES (C	ptional)	
	Government Corner	□ Co	ntrol		Section 1	NAD27		
menorance propriations Growthand processors programme	Meander	□ Pro	operty	П	Zone NAD83 Epoch	NAD27	□ NAD83	
	Rancho		ner	以	Elev. Vert. Datum:			
	Date of Survey 11	101		***	Meas. Units:	Metric □	NAVD88 Imperial	
Corner –	Left as found 🔼 Found and ta	gged П	Establi	shed [l Reestak	olished 🛚	Rebuilt	Common Common of
_	pe of corner found: Evidence used							er:
SEE OF	HER SIDE	Andrew Constitution and Antology of the confidence on a secure of the confidence of		The state of the s				

								98/d-19
***************************************						A ACCIDENT		
A 1								
	physical condition of the monumen							
DEE OIF	ER SIDE					TO THE PARTY OF TH	***************************************	***************************************
								t 10 (table to the left) which consists any playing at a party consists any excess the party
Province County for Males Calls As As As As A STOTE Following as As As As Apple of the STOTE Williams As			**************************************				.	
	SURVEYOR'S STATEME	ENT				1.5	DLAND	SUS
This Corner Recor	d was prepared by me or under m	av direction	in confe	armance	a with	18%	EU W. C.	
		iy direction					Evo 9.2.	3/50
the Land Surveyor'	SACT ON JUNE 15			007	MORPHONIS ALCOY			05
Signed Kut	P.L.Sor R	.C.E. No	694	4	entronement on his transportation is a		L.S. 6944	
							OF CALIF	O BERN
	COUNTY SURVEYOR'S STAT	rement					S. OHU.	
This Corner Record	was received 501 T	2002-	SPERMAN AND AND AND AND AND AND AND AND AND A				O LAND S	31/5
and examined and	iled Joly 15	2002) -gwen				OT L. TUR	
L. Landerson				2			~ 00 00 %	· / / /
Signed by	S. Turny P.L.SorR	.U.E. No. <u>«</u>	and said Colombia	<u> </u>		*	Exp. 09-30	-04
Title 120	6. Suckeyal						No. 552	3 / E / /
							F OF CAL	IFO!
County Surveyor's	S Comment							

		errore error arrevers errore error error a to to to the total before an epitandonomic				Construence and Lines (AMA) (by page 1995) and the construence of the Armstein of the Construence of the Armstein of the Construence of the Constr		Marie Control of the September and the September 2 part of the consequence and page of
*QAVINATURITAN NO 1940 AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA					andra charactery (managers)			



8 - FD. 3/4" I.P., LS 5122 (USE TACK IN TAG AS REF. Pt.) IN MON. BOX

R - FD, CHIS, X" ON T.C.; 95' SW OF 6' CH. LK. FENCE NW AT SW PL OF SCHOOL

S - SET CHIS. - - T.C., NW RET., N COR. T - " , W GZ.

U - SET CHIS. -; The; ON & + OF SE SIDE OF CONC. BASE FOR ST. LT. A0289, MHICH IS NEAR SW CURB RET., W COR.

