


CORNER RECORD

Agency Index 3771-A

Document Number _____

City of _____ County of MERCED, California

Brief Legal Description N.W. CORNER PARCEL 2 PER 109-P.M.-25.



T.10S., R.11E.

CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other

Date of Survey MAY 21, 2019

COORDINATES (Optional)

N. _____ E. _____

Elevation _____

Units Metric U.S. Survey Foot

Horizontal Datum _____

Zone _____ Epoch Date _____

Vertical Datum _____

Complies with Public Resources Code §§8801-8819

Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:

Corner/Monument: Left as found Established Rebuilt Pre-Construction

Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:

See sheet #2 for description(s):

MONUMENT MAY BE DISTURBED DUE TO CONSTRUCTION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with

the Professional Land Surveyors' Act on 6 Nov 2019

Signed [Signature] P.L.S. or R.C.E. No. 9417



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 23, 2019


and examined and filed JANUARY 3, 2020

Signed [Signature] P.L.S. or R.C.E. No. 8664

Title COUNTY SURVEYOR

County Surveyor's Comment





SECTION 36
T.9S R.11E.

FOUND CUT X

FOUND CUT X

N.W. COR. PARCEL 2
FOUND 1 1/4" GALVANIZED IRON PIPE
WITH NO TAG IN MONUMENT WELL.

HENRY MILLER AVENUE

FOUND MAG & TIN

PP - O

FOUND 80D NAIL

PARCEL 3
109-PM-25
SECTION 1
T.10S. R.11E.

PARCEL 2
109-PM-25
SECTION 1
T.10S. R.11E.