


NO. 379c 3798

COUNTY OF Merced T. 10 South R. 13 East M.D.B. & MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT February 19, 1976



Northwest corner, Section 20, Township 10 South, Range 13 East

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

4" x 4" Redwood Post at 1 foot below the groundline.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

No PHYSICAL OBJECTS AVAILABLE FOR SWING TIES

5278.75 SOUTHERLY OF THE NORTHWEST CORNER OF SECTION 17, 10/13.



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON April 25, 1976 19 76

SIGNED: Johnny E. Davis
L.S. or R.C.E. No.: L.S. 4156

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19 _____
AND EXAMINED AND FILED _____ 19 _____

BY: _____
TITLE: _____

DOCUMENT No. 3798

STATEMENT ON BACK OF SHEET YES NO

SEAL