


CORNER RECORD

Agency Index 3829
Document Number _____

City of _____ County of MERCED, California
Brief Legal Description N.W. COR. SECTION 6 T.10S. R.11E. MDB&M.



T.10S., R.11E.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

Date of Survey MAY 21, 2019

COORDINATES (Optional)

N. _____ E. _____
Elevation _____
Units Metric U.S. Survey Foot
Horizontal Datum _____
Zone _____ Epoch Date _____
Vertical Datum _____

Complies with Public Resources Code §§8801-8819
 Complies with Public Resources Code §§8890-8902

PLS Act Ref.: 8765(d) 8771 8773 Other:
Corner/Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:
 See sheet #2 for description(s):

MONUMENT MAY BE DISTURBED DUE TO CONSTRUCTION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
the Professional Land Surveyors' Act on 6 NOV 2019
Signed [Signature] P.L.S. or R.C.E. No. 9417




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received DECEMBER 23, 2019
and examined and filed JANUARY 3, 2020
Signed Zach T. Janz P.L.S. or R.C.E. No. 8664
Title COUNTY SURVEYOR



County Surveyor's Comment



SCALE: 1" = 30'

S.E. 1/4
SECTION 36
T.9S. R.10E.

S.W. 1/4
SECTION 31
T.9S. R.11E.

R.10E.
R.11E.

FOUND 80D NAIL

HENRY MILLER AVENUE

N.W. COR. SEC. 6
FOUND 2 1/2" IRON PIPE
NO TAG IN MONUMENT WELL.

T.9S.
T.10S.

T.9S.
T.10S.

111.01'

FOUND N&S IN P.P.

49.22'

FOUND N&S IN FENCE POST

N.E. 1/4
SECTION 1
T.10S. R.10E.

R.10E.
R.11E.

DIRT
ROAD

N.W. 1/4
SECTION 6
T.10S. R.11E.