


CORNER RECORD

Document Number 3861
County of MERCED, California

City of _____
Brief Legal Description NORTHWEST CORNER OF 30, T.10S., R.11E., M.D.B.&M., AS SHOWN ON 26 R.S. 47, M.C.R.



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other

COORDINATES(Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Date of Survey OCTOBER 29, 2014

Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

See Page 2 of 2

A description of the physical condition of the monument as found and as set or reset:

See Page 2 of 2

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the land Surveyors' Act on OCTOBER 30, 2014.

Signed Zach T. Janz P.L.S. No.: 8664



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received Nov. 5, 2014 and examined and filed Nov. 6, 2014.


Signed [Signature] P.L.S. or ~~P.C.E.~~ No.: 4895

Title County Surveyor

County Surveyor's Comment _____



24|19
25|30



60'
30'

RD.

FOUND 2" IRON PIPE PER 26 R.S. 47, M.C.R.
RUSTED AND CRUMBLING. SET 3/4" I.P. WITH TAG
"LS 8664" IN CENTER OF 2" IRON PIPE, DOWN 2.0'

(2657.31') (26 R.S. 47, M.C.R.)

WARD

PHILLIPS

RD.