

4030

CORNER RECORD

COUNTY OF Merced T. 8S R. 15E Mt. Diablo MERIDIAN CALIFORNIA
 CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT 9-14-1976



South 1/4 corner Section 32, T8S, R15E

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


Found 1-1/8 iron rod down 1.35 below road surface
 No tag

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 44.76 North West from nail & shiner on North side of power pole
- 90.06 South West from nail & shiner on South side of railroad tie
- 31.99 South from nail & shiner on East side of 4 x 4 pole
- 112 ft. West from centerline of Athalone Road, running North



SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON Jan. 24, 1975
 SIGNED: *Johnny E. Davis*
 L.S. or R.C.E. No.:

SEAL

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED _____ 19_____
 AND EXAMINED AND FILED _____ 19_____
 BY: _____
 TITLE: _____

DOCUMENT No. 4030

STATEMENT ON BACK OF SHEET YES NO