

CORNER RECORD

COUNTY OF MERCED T. 6 S R. 13 E M.D. MERIDIAN CALIFORNIA
 CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER
 CORNER IDENTIFICATION — DATE OF VISIT May 4 1984




CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH
Found 1 1/2" outside diameter iron pipe two feet down at the west quarter corner of section 34

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED
Set 5/8" iron rod with county surveyor tag over 1 1/2" iron pipe.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
 STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
 ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)



Prepared by
 Gary Grinder
 Party Chief
 Gg

May 11, 1984

Tie in F.B. 706 p. 58

SURVEYOR'S CERTIFICATE
 THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON _____ 19_____
 SIGNED: _____
 L.S. or R.C.E. No.: _____

COUNTY SURVEYOR'S CERTIFICATE
 THE CORNER RECORD WAS RECEIVED May 11 1984
 AND EXAMINED AND FILED 1/20/1984 1984
 BY: [Signature]
 TITLE: County Surveyor
 DOCUMENT No. 4033
 STATEMENT ON BACK OF SHEET YES NO

SEAL