

CORNER RECORD

COUNTY OF MERCED T. 8 S. R. 15 E. M.D.B. & MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT JUNE 4, 1987



SOUTHWEST CORNER SECTION 35 8/15

SANDY MUSH ALIGNMENT & POOLE ROAD ALIGNMENT

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 3/4" IRON PIPE W/ 1/2" BRASS CAP W/ CROSS IN CENTER 6" DOWN.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

77.60' SE of @ s/s of PP.
6.0' S. of PL E. & W.
15.5' E. of PL 1000' ± N. (N/S Dutchman Creek)
23.0' W. of Fence Line N.
6' ± S. of Fence Line E.
23.75' SW of @ s/s Cor. Fence Post.

J.N. 86-030

F.B. 579/5

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON JUNE 12, 1987

SIGNED: William O. Gentry
L.S. or R.C.E. No.: 2737

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED LS 45023 1987 AND EXAMINED AND FILED 7/11 1987

BY: Ray [Signature]
TITLE: Deputy Co. Surveyor

DOCUMENT No. 4094

STATEMENT ON BACK OF SHEET

