


CORNER RECORD

Document Number 4109

City of _____ County of Merced, California

Brief Legal Description S 1/4 Corner Section 32 8/14



CORNER TYPE

- Government Corner Control
- Meander Property
- Rancho Other
- Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

A description of the physical condition of the monument as found and as set or reset: _____

Fd 1" Iron rod

Monument well set over existing monument. 8-30-93

F.B. 658-37

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept. 7 1993.

Signed Lawrence L. Bowers L.S. or R.C.E. Number _____




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPT. 1993 and examined

and filed SEPT. 16, 1993.

Signed Roy L. Turney Title DEP. CO. SUR.



County Surveyor's Comment _____

