


**CORNER RECORD**

Document Number 4117

City of \_\_\_\_\_

County of MERCED, California

Brief Legal Description SOUTH 1/4 CORNER SECTION 15, T6S, R13E, MDM



**CORNER TYPE**

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 5-19-04

**COORDINATES (Optional)**

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ NAD27  NAD83   
NAD83 Epoch \_\_\_\_\_  
Elev. \_\_\_\_\_  
Vert. Datum: NGVD29  NAVD88   
Meas. Units: Metric  Imperial

Corner - Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
USED THE S.E. CORNER OF SEC. 15 & 500' WITNESS CORNER TO THE S.W. CORNER OF SEC. 15 TO REESTABLISH THE 1/4 CORNER AS SHOWN ON "FINAL MAP OF CHINA CANYON RANCH," RECORDED IN 56 O.P. 23, M.C.R. & "PARCEL MAP FOR BERT CRANE SR." RECORDED IN 95 P.M. 33, M.C.R.

A description of the physical condition of the monument as found and as set or reset: SET 1 1/4" IRON PIPE WITH 2" BRASS CAP


**SURVEYOR'S STATEMENT**

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on MAY 20, 2004  
Signed David D. Heinrich P.L.S. or R.C.E. No. 7621



**COUNTY SURVEYOR'S STATEMENT**

This Corner Record was received 5-20-04  
and examined and filed 5-29-04  
Signed Roy L. Turney P.L.S. or R.C.E. No. 5523  
Title Dep. Co. Sur.



County Surveyor's Comment \_\_\_\_\_

SEC.  
15  
T.6.S., R.13E., M.D.M.

