


CORNER RECORD

Document Number 4526(2)
 County of Merced, California

City of _____
 Brief Legal Description See sketch

CORNER TYPE	COORDINATES(Optional)
<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> <p>Government Corner <input checked="" type="checkbox"/> Meander <input type="checkbox"/> Rancho <input type="checkbox"/></p> </div> <div style="width: 45%;"> <p>Control <input type="checkbox"/> Property <input type="checkbox"/> Other <input type="checkbox"/></p> </div> </div> <p>Date of Survey <u>12-3-14</u></p>	<p>N: _____ E: _____ Zone _____ NAD27 <input type="checkbox"/> NAD83 <input type="checkbox"/> NAD83 Epoch _____ Elev. _____ Vert. Datum: NGVD29 <input type="checkbox"/> NADV88 <input type="checkbox"/> Meas. Units: Metric <input type="checkbox"/> Imperial <input type="checkbox"/></p>



Corner - Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Replaced monument after road reconstruction.

A description of the physical condition of the monument as found and as set or reset: As described

SURVEYOR'S STATEMENT


This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 12-3-2014.
 Signed [Signature] P.L.S. or R.C.E. No.: 4403



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received December 8, 2014 and examined and filed December 15, 2014.
 Signed [Signature] P.L.S. or R.C.E. No.: 4895
 Title County Surveyor
 County Surveyor's Comment _____





SCALE 1" = 40'

