


CORNER RECORD

Document Number 33

City of \_\_\_\_\_ County of MERCED, California

Brief Legal Description E Intersection Minturn Rd. & Harvey-Pettit Rd.  
9/15



CORNER TYPE

Government Corner  Control   
Meander  Property   
Rancho  Other   
Date of Survey 2-28-95

COORDINATES  
(Optional)

N. \_\_\_\_\_  
E. \_\_\_\_\_  
Zone \_\_\_\_\_ Datum \_\_\_\_\_  
Elev. \_\_\_\_\_

Corner — Left as found  Found and tagged  Established  Reestablished  Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:  
Found 1/4" Iron Pipe with nail in monument well with no lid.

A description of the physical condition of the monument as found and as set or reset: \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Oct. 24 1995.


Signed [Signature] L.S. or R.C.E. Number \_\_\_\_\_



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 1995 and examined and filed OCTOBER 31, 1995.

Signed [Signature] Title DEP. CO. SUR.



County Surveyor's Comment \_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

