


CORNER RECORD

Document Number 67-JJ

City of _____ County of MERCED, California

Brief Legal Description CENTER-LINE MONUMENT OF FLOWER STREET



T.6S./R.11E.

CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey January 06, 2017

COORDINATES (Optional)

N. _____
E. _____
Zone NAD 27 NAD 83
Elev. _____
Vert. Datum: NAVD 29 NAVD 88
Meas. Units: METRIC IMPERIAL

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
Found 3/4 inch iron pipe, 13 inches deep on the centerline of Flower Street, ±20 feet north of the centerline of Lettau Ave. as shown on "Map of Survey for Fred R. Stephenson" filed as BC-295 at the Merced County Surveyor's Office, shown as 3/4" iron rod on BC-017. Surveyed in conformance with the PLS Act Section 8771 prior to construction. See page 2.

A description of physical condition of the monument as found and as set or reset: _____
Found 3/4 inch iron pipe, 13 inches down.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on JAN. 25 20 17.

Signed [Signature] P.L.S. or R.C.E. Number 9273



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received JANUARY 30 20 17 and examined and filed FEBRUARY 2 20 17.

Signed Zach T. Janz P.L.S. or R.C.E. Number 8664
Title COUNTY SURVEYOR



County Surveyor's Comment _____

LEGEND

- ⊕ CHISELED "X"
IN CONCRETE
- ⊙PP NAIL & SHINER
IN POWER POLE



NOT TO SCALE

