

CORNER RECORD

Document Number 639

City of PLANADA

County of MERCED, California

Brief Legal Description WEST 1/4 CORNER, SEC 27 T7S, R15E, MDM



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 6-16-04

COORDINATES (Optional)

N. _____
E. _____
Zone _____ NAD27 NAD83
NAD83 Epoch _____
Elev. _____
Vert. Datum: NGVD29 NAVD88
Meas. Units: Metric Imperial

Corner - Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
FOUND 3/4" IRON PIPE WITH L.S. 3733 TAG IN MONUMENT WELL PER CORNER RECORD #639 FILED APRIL 29, 2003.

A description of the physical condition of the monument as found and as set or reset: MONUMENT IN GOOD CONDITION - MAY BE DESTROYED WITH CONSTRUCTION PROJECT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyor's Act on 8-19-2004

Signed David D. Heinrichs P.L.S or R.C.E. No. LS 7621




COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 8-19-04

and examined and filed 9-7-04

Signed Roy L. Turney P.L.S or R.C.E. No. 5523

Title Deputy Co. Surveyor



County Surveyor's Comment _____

