


CR # 713

CORNER RECORD

COUNTY OF MERCED T. 5 N. R. 12 E. M.D.B.# MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT JULY 9, 1991



NORTHWEST CORNER SECTION 11 5/12

LOONEY ROAD S. ~ MONTE VISTA AVE. E. & W.

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 1 1/4" IRON PIPE W/WOOD PLUG - NO TAG - 9" DOWN

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

KNOCKED PLUG DOWN & CEMENTED L.S. 2737 BRASS TAG IN PIPE & SET 2' TIES N. & E.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD

STATIONS USED: MGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____

ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (E) _____


SKETCH: (Include reference tie or witness points, remarks and topo of area)

ON C/L ROAD E. & W.
 8.0' E. OF C/L ROAD S.
 49.95' NW OF @ NE/S JCT PP.
 36.34' NW OF 1/2" I.P. - L.S. 4379 - DOWN 4".
 89.22' NW OF @ W/S TRANS. PP.
 60.43' NE OF @ E/S 5" DIAM. POST - 5' HIGH.
 23.80' N. OF PL E. - OMIT FIRST 2 POLES.
 18.50' W. OF PL S. - OMIT FIRST 3 POLES.

See P.M. BK. 60 Pg. 3

J.N. 91-041

F.B. 587/4



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON JULY 9, 1991

SIGNED: William O. Gentry

L.S. or R.C.L. No. 2737

EXPIRES: 6-30-1992

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED Sept. 30, 1992 AND EXAMINED AND FILED 8-22 1991

BY: [Signature]

TITLE: Deputy County Surveyor

DOCUMENT No. #713

STATEMENT ON BACK OF SHEET YES NO