


CORNER RECORD

Document Number 763 CC

City of _____ County of MERCED, California

Brief Legal Description E. OF VAN CLIEF RD. & ST. RT. 140
SECTION 23/24 T. 7S. R. 10E. MDM



CORNER TYPE

Government Corner Control
Meander Property
Rancho Other
Date of Survey 2/5/92

**COORDINATES
(Optional)**

N. _____
E. _____
Zone _____ Datum _____
Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: FOUND 1 1/4" IRON PIPE AT E. VANCLIEF RD. PER MERCED COUNTY ROAD SURVEY 5-727

A description of the physical condition of the monument as found and as set or reset: MONUMENT IS IN GOOD CONDITION WITH 2' RP'S & SPIKE OVER IT.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 2-5- 1992.

Signed Ralph Scheel L.S. or R.C.E. Number 3730



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 3-13- 1992 and examined and filed 3-20- 1992.

Signed Roy L. Turney Title Dep. Co. Surveyor



County Surveyor's Comment _____

