


CORNER RECORD

Agency Index 882
Document Number _____

City of _____ County of Merced, California
Brief Legal Description Corner Common to Sections 17,18,19,and 20, T9S; R9E; MD Base and Meridian

CORNER TYPE

COORDINATES (Optional)



- Government Corner Control
 Meander Property
 Rancho Other

N. _____ E. _____
 Elevation _____
 Units Metric U.S. Survey Foot
 Horizontal Datum _____
 Zone _____ Epoch Date _____
 Vertical Datum _____
 Complies with Public Resources Code §§8801-8819
 Complies with Public Resources Code §§8890-8902

Date of Survey October 1, 2018

- PLS Act Ref.: 8765(d) 8771 8773 Other:
 Corner/
 Monument: Left as found Established Rebuilt Pre-Construction
 Found and tagged Reestablished Referenced Post-Construction

Narrative of corner identified and monument as found, set, reset, replaced, or removed:
 See sheet #2 for description(s):

Found 3/4" O. D. Iron Pipe with Orange Plastic Plug Stamped "LS 3664" down 0.6' in Well Monument one half (0.5) mile North of the Intersection of (SR-33) and Marshall Road.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Professional Land Surveyors' Act on October 30, 2018
 Signed *Craig L. Chapman* P.L.S. or R.C.E. No. L 9391



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received NOVEMBER 30, 2018
 and examined and filed DECEMBER 28, 2018
 Signed *Zachary T. Janz* P.L.S. or R.C.E. No. 8664
 Title COUNTY SURVEYOR



County Surveyor's Comment

3/4" IRON PIPE PER TAGGED LS 8664 PER 55 RS 1

