

CORNER RECORD

COUNTY OF FRESNO T. 11 S. R. 12 E M.D. REM MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION - DATE OF VISIT JAN 17 1992



N.W. COR. SECTION 13 1/2

VALERIA AVE. & MILLOUX AVE.

CORNER - LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER RESULT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

FOUND 3/4" IRON PIPE DOWN 0.50' BELOW ASPHALT
UNABLE TO FIND TAG. NO TAG SET

PHYSICAL DESCRIPTION OF MONUMENTS RESULT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & OS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (N) _____ EASTINGS (E) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 91.41' S.W. CORNER OF WOOD FRAME BUILDING
- 61.26' S.W. OF NAIL & SHINER IN POWER POLE
- 42.40' S.E. OF 3/4" IRON PIPE DN. 0.50' TAG LS. 4156
- 35.25' S.E. OF COR. BRICK BUILDING.
- 22.63' N.E. OF COR. BRICK BUILDING
- 87.34' N.W. OF NAIL & SHINER IN POWER POLE
- 71.88' N.W. OF COR. OF TIN BUILDING
- 3.5' SOUTH OF E STRIPE RUNNING EAST & WEST
- 2.00' N. OF NAIL & SHINER SET FLUSH IN P.V.M.T.
- 2.00' W. OF NAIL & SHINER SET FLUSH IN P.V.M.T.

FB 145/54

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON MAY 20 1992

SIGNED: [Signature]

L.S. No. 4823

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED JUNE 1 1993 AND EXAMINED AND FILED MARCH 24 1993

BY: [Signature]

TITLE: SENIOR ENGINEER

DOCUMENT No. 5256

STATEMENT ON BACK OF SHEET

YES NO