


CORNER RECORD

Document Number 1990 - A & B

City of _____ County of MERCED, California

Brief Legal Description SOUTHEAST COR. PAR. 1 & SOUTHWEST COR. PAR. 2. OF 51-PM-2A, Mer. Co REC. SECT. 29 & 30 T. 7 S. R. 12 E. M.D.M.



CORNER TYPE

- Government Corner
- Meander
- Rancho
- Date of Survey 2-10-92
- Control
- Property
- Other

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: 2-3/4" IRON PIPES W/PLASTIC PLUGS STAMPED L.S. 3733

A description of the physical condition of the monument as found and as set or reset: MONUMENTS APPEAR TO BE IN GOOD CONDITION

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on 2-10 19 92.


Signed Ralph Scheel L.S. or R.C.E. Number 3730



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received 3-13- 19 92 and examined and filed 3-20- 19 92.

Signed Roy L. Turney Title Dep. Co. Surveyor



County Surveyor's Comment _____

* SOUTHEAST CORNER PARCEL 1 & SOUTHWEST CORNER PARCEL 2
 OF ~~51~~ PM 24 MER CO. REC., IN SECTIONS 29 & 30,
 T. 7 S., R. 12 E., M. 1 D., ~~13~~ M.

