


CORNER RECORD

Document Number 2291

City of _____ County of _____, California

Brief Legal Description S.E. Corner Section 4 6/11



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey _____

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

A description of the physical condition of the monument as found and as set or reset: Found 3/4" Iron Pipe,
down 0³, orange plastic tag (L.S. 3733) has been
mutilated.
Monument box set over existing monument.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on Oct 24 1995.


Signed [Signature] L.S. or R.C.E. Number _____



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received OCTOBER 1995 and examined
 and filed OCTOBER 30, 1995.

Signed [Signature] Title DEP. CO. SURVEYOR



County Surveyor's Comment _____

