


#2318

CC TER RECORD

COUNTY OF Merced T. 9 S R. 15 E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION - DATE OF VISIT April 17, 1975



Northwest corner Section 14, T 9 S, R 15 E.

CORNER - LEFT AS FOUND [X] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 2" O.D. pipe 1.0 below road surface.


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Also found 1-1/4" O.D. pipe 30' west of 2" O.D. pipe and 1-1/4" O.D. pipe tagged L.S. 656 30' West and 30' South of Block Corner.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____ ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 27.97 West from nail & shiner in power pole.
65.52 Northeast from nail & shiner in power pole.
146.84 North from nail & shiner in power pole.
30' East from 1-1/4" O.D. pipe.
42.29 Northeast from 1-1/4 O.D. pipe plugged L.S. 656.



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 30, 1979

SIGNED: [Signature]

L.S. or R.C.E. No.: 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. 2318

STATEMENT ON BACK OF SHEET

YES [] NO []