


CORNER RECORD

Document Number 2480

City of _____ County of MERCED, California

Brief Legal Description So. 1/4 Cor SEC. 18 1/2



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 8-11-92

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:

Ed 1 1/2 I.P. TAG/ R.C.E. 13760 IN MON. BOX. AS PER 39 P.M.-23

_____ BK 658-21

A description of the physical condition of the monument as found and as set or reset: _____

O.K. 8-30-93

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on Sept 7 19 93.

Signed [Signature] L.S. or R.C.E. Number _____



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received SEPT. 19 93 and examined and filed SEPT. 16, 19 93.

Signed [Signature] Title DEP. Co. SUR.

County Surveyor's Comment See P.M.- BK 37 Pg. 15



THIS NOTCH IN TOP
 OF 1/4" IRON PLATE
 WELDED VERTICALLY
 INTO 6" DIA. x 4' TALL
 IRON POST FOR EAST
 SIDE OF CABLE GATE.

DIRT RD.
 GRAVEL RD.

FD. NAIL & SHINER
 IN NW SIDE OF
 POWER POLE. w/ TRANSF.

FD. 1 1/2" I.P., R.C.E. 13760,
 IN MON. BOX.
 S. 1/4 COR. SEC. 18 5/12

SECTION 18
 SECTION 19

EAST AVENUE

30.00'

40.04'

66.91'

43.60'

FD. 3/4" I.P., L.S. 4403
 1' S. OF E/W FENCE
 LINE.

FD. NAIL & SHINER
 IN NE SIDE OF
 TRANS. POLE



POINTS WERE TIED OUT PRIOR TO PAVING
 EFFORT BY MERCED COUNTY DEPARTMENT
 OF PUBLIC WORKS