**CORNER RECORD** Agency Index **Document Number** County of Merced Brief Legal Description East 1/4 Corner of Section 19; T9S; R9E; Mount Diablo Base and Meridian **CORNER TYPE** COORDINATES (Optional) N. Government Corner Elevation Control X U.S. Survey Foot Meander Property Units Metric Rancho Other Horizontal Datum **Epoch Date** Zone Date of Survey October 1, 2018 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) X 8771 8773 Other: Left as found Established Rebuilt Pre-Construction Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Found 3/4" O.D. Iron Pipe with Orange Plastic Plug stamped "LS 3664" down 0.4' in a monument well in the Intersection of (SR-33) and Marshall Road. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with CRAIG L. CHAPMAN the Professional Land Surveyors' Act on October 30, 2018 L 9391 P.L.S. or R.C.E. No. Signed COUNTY SURVEYOR'S STATEMENT This Corner Record was received NOVEMBER 30, 2018

and examined and filed

DECEMBER 28, 2018.

Signed

P.L.S. or R.C.E. No. 8664

ZACHARY T. JANZ

LS8664

OUNTY SURVEYOR Title

**County Surveyor's Comment** 

3/4" IRON PIPE TAGGED LS 8664 PER 55 RS 1

