CORNER RECORD Agency Index **Document Number** City of County of Merced Brief Legal Description East 1/4 Corner of Section 19; T9S; R9E; Mount Diablo Base and Meridian **CORNER TYPE** COORDINATES (Optional) E. Government Corner Control Elevation X U.S. Survey Foot Meander Property Units Metric Other Rancho Horizontal Datum Epoch Date Zone Date of Survey October 1, 2018 Vertical Datum Complies with Public Resources Code §§8801-8819 Complies with Public Resources Code §§8890-8902 PLS Act Ref.: 8765(d) X 8771 Other: Left as found Established Pre-Construction Rebuilt Corner/ Monument: Found and tagged Reestablished Referenced Post-Construction Narrative of corner identified and monument as found, set, reset, replaced, or removed: See sheet #2 for description(s): Found 3/4" O.D. Iron Pipe with Orange Plastic Plug stamped "LS 3664" down 0.4' in a monument well in the Intersection of (SR-33) and Marshall Road. SURVEYOR'S STATEMENT This Corner Record was prepared by me or under my direction in conformance with CRAIG L. the Professional Land Surveyors Act on October 30, 2018 **CHAPMAN** L 9391 Signed P.L.S. or R.C.E. No. EXP 09/30/18 COUNTY SURVEYOR'S STATEMENT NOVEMBER 30, 2018 This Corner Record was received DECEMBER 28, 2018 ZACHARY T. JANZ and examined and filed P.L.S. or R.C.E. No. 8664 Signed LS8664 COUNTY SURVEYOR Title County Surveyor's Comment

3/4" IRON PIPE TAGGED LS 8664 PER 55 RS 1

