


261

CORNER RECORD

COURTY OF Merced T. 9 S. R. 15 E. Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [] MEANDER [] RANCHO [] CONTROL [] OTHER [X]

CORNER IDENTIFICATION — DATE OF VISIT April 14, 19 76



Northwest corner of Lot 18, Block 19, (Section 19) of the Bliss Ranch Subdivision on file in Volume 7 of plats at page 45 of M.C.R.

CORNER — LEFT AS FOUND [] FOUND AND TAGGED [X] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


Found 4 x 4 redwood post 0.25 above ground line with 2" O.D. pipe 0¹ West of redwood at 0⁹ below ground.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____ ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

2.71 East from nail & shiner in 6" x 8" brace post.
2.92 West from nail & shiner in 6" x 8" brace post.



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 29, 19 79 LS. 4156 SIGNED: John E. Davis L.S. or R.C. No.: 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____ BY: _____ TITLE: _____ DOCUMENT No. 2677-F STATEMENT ON BACK OF SHEET YES [] NO []