


14

CORNER RECORD

Document Number 2690

City of _____ County of MERCED, California

Brief Legal Description N.E. COR SECT 29, T10S R12E MDB&M.



CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other
 Date of Survey 6-14-90

COORDINATES (Optional)

N. _____
 E. _____
 Zone _____ Datum _____
 Elev. _____

Corner — Left as found Found and tagged Established Reestablished Rebuilt


Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner: 3/4" I. PIPE - NO TAG SEE 37 PM 22 & 18 RS 25

A description of the physical condition of the monument as found and as set or reset: MONUMENT IN GOOD CONDITION, DOWN 0³ IN PAVEMENT

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with the Land Surveyors' Act on JUNE 14 1990.

Signed Ralph N. Scheel, Jr. L.S. or R.C.E. Number LS3730



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received August 1990 and examined and filed August 22, 1990.

Signed Roy L. Turney Title Dep. Co. Surveyor

County Surveyor's Comment COR. # 2690 ok.



20 21
29 28

T105 RIZE
MDBEM

