

3021A

COI RECORD

COUNTY OF Merced T. 10 S. R. 9 E. M.D.B. & MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [x] MEANDER [] RANCHO [] CONTROL [] OTHER []

CORNER IDENTIFICATION — DATE OF VISIT January 17, 1977



North quarter corner of Section 28

CORNER — LEFT AS FOUND [x] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT []

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

1" O.D. x 28" pipe with plug marked L.S. 4156 - 1 foot below ground line

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD [] STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

16.75 ft. Southwest of Chisled X in 42" concrete stand pipe.

30.28 ft. Southeast nail & shiner in 4" x 4" white post.

23.44 ft. Southwest of NAIL IN S.E. CORNER OF CONCRETE PAD

SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION, IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON January 29, 1977

SIGNED: Johnny E. Davis



COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. 3021A