


3108

CO RNER RECORD

COUNTY OF Merced T. 9S R. 15E M.D.B. & M. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [X] MEANDER [] RANCHO [] CONTROL [] OTHER [X]
CORNER IDENTIFICATION — DATE OF VISIT September 22, 1976



West 1/4 corner Section 8

CORNER — LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [X] REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Set 1" O.D. pipe with plastic plug marked L.S. 4156 at groundline AT PROPORTIONAL DISTANCE BETWEEN THE N.W. CORNER AND THE S.W. CORNER OF SECTION 8, 9/15.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

38.65 EASTERLY from nail & shiner in 4" x 6" post
44.82 N.E. FROM NAIL & SHINER IN 4" x 5" FENCE POST
1.49 S.E. FROM NAIL & SHINER IN 4" x 6" POST EXTENDING 9 1/2' ABOVE GROUNDLINE



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON L.S. 4156 10/20 19 80

SIGNED

Handwritten signature of James E. Davis

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED Feb 25 19 80 AND EXAMINED AND FILED BY: Walt Mitchell

TITLE:

DOCUMENT No. 3108

STATEMENT ON BACK OF SHEET

YES [] NO []