


NO. 372

CO R R RECORD

COUNTY OF Merced T. 9S R. 15E M.D.B. & M. MERIDIAN CALIFORNIA
CORNER TYPE: GOV'T. CORNER MEANDER RANCHO CONTROL OTHER
CORNER IDENTIFICATION — DATE OF VISIT April 16, 1975



Northwest corner of Lot 8, Block 16, (Section 16) as shown on the Map of the Bliss Ranch Subdivision filed in Volume 7 of plats at Page 39, M.C.R.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1" O.D. pipe with plastic plug marked L.S. 3733, in remains of a 4 x 4 redwood post at 1.5' below groundline


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Offset monument
Set 1" O.D. pipe 35 feet south of original corner at 90° angle to the north line of northwest quarter of Section 16

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- Ties to Section Corner
- 23.69 Southeast from nail & shiner in corner fence post
- 63.16 Northwest from nail & shiner in power pole
- 71.49 Northeast from "X" on 36" standpipe
- 13.43 South from 1" O.D. pipe
- 48.78 South from nail & shiner in power pole



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT
L.S. 4159 ON Feb. 20 1980
WALTER MITCHELL
L.S. of C.C.E. No. H136

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED Feb. 25 1980 AND EXAMINED AND FILED BY: Walter Mitchell
TITLE: _____
DOCUMENT No. 3112
STATEMENT ON BACK OF SHEET YES NO

SEAL