


NO. 3117

CORNER RECORD

COUNTY OF Merced T. 9S R. 15E M.D.B. & M. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [ ] MEANDER [ ] RANCHO [ ] CONTROL [ ] OTHER [X]

CORNER IDENTIFICATION — DATE OF VISIT April 17, 1975



Northwest corner of Lot 4, Block 16, (Section 16,) as shown on the Map of the Bliss Ranch Subdivision on file in Volume 7 at Page 39, M.C.R.

CORNER — LEFT AS FOUND [X] FOUND AND TAGGED [ ] REESTABLISHED OBLITERATED CORNER [ ] REBUILT [ ]

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 1-1/2" O.D. pipe with TAG L.S. 656 at 1.0 below groundline Also found 3" x 4" redwood 30.30 south of corner


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET REFERENCE MONUMENT: 1" O.D. x 28" GALVANIZED IRON PIPE TAGGED L.S. 4156 AT 35.00 NORTH

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [ ] SECOND [ ] THIRD [ ] STATIONS USED: NGS (USC & GS) [ ] STATE [ ] COUNTY [ ] OTHER [ ] STATION \_\_\_\_\_ STATION \_\_\_\_\_ ZONE \_\_\_\_\_ ELEVATION \_\_\_\_\_ NORTHINGS (Y) \_\_\_\_\_ EASTINGS (X) \_\_\_\_\_

SKETCH: (Include reference tie or witness points, remarks and topo of area)

16.71 North from nail & shiner in fence post 46.21 Northeast from mark and paint spot on 15' air vent



SURVEYOR'S CERTIFICATE THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON FEB. 20 1980 SIGNED: [Signature] L.S. or P.E.C. No.: 4156

COUNTY SURVEYOR'S CERTIFICATE THE CORNER RECORD WAS RECEIVED Feb. 25 1980 AND EXAMINED AND FILED BY: Walter Mitchell TITLE: \_\_\_\_\_

DOCUMENT No. 3113 STATEMENT ON BACK OF SHEET YES [ ] NO [ ]

SEAL