


#3119

CORNER RECORD

COUNTY OF Merced T 9 S. R 15 E Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION -- DATE OF VISIT June 19, 1980



Northwest corner of Lot 24, Block 17 (Section 17) of the Bliss Ranch Subdivision on file in Volume 7, Page 40, M.C.R.

CORNER -- LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

4" x 4" redwood with 1" O.D. pipe in center with plug marked L.S. 3733. Corner was destroyed in canal construction.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Reset from swing ties, 1" O.D. pipe tagged R.C.E. 12700 @ 0.6 feet below ground line.


CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 84.94 Northeast from nail & shiner in power pole.
- 39.69 Northeast from "X" on northwest side of 30" standpipe.
- 269.92 Southeast from nail & shiner in power pole.

SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 25 June No. 12700

SIGNED: Frank Staveland
L.S. or R.C.E. No. 12700



COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED _____ 19____
AND EXAMINED AND FILED _____ 19____
BY: _____
TITLE: _____

DOCUMENT No. 3119

STATEMENT ON BACK OF SHEET YES NO