


NO. 3120

CORNER RECORD

COUNTY OF Merced T. 9S R. 15E M.D.B. & M. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [] MEANDER [] RANCHO [] CONTROL [] OTHER [x]
CORNER IDENTIFICATION - DATE OF VISIT December 1976



Northwest corner of Lot 20, Block 18, (Section 18) as shown on the Map of the Bliss Ranch Subdivision on file in Volume 7 of plats at Page 40, M.C.R.

CORNER - LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT [x]

PHYSICAL DESCRIPTION OF CORNER FOUND, EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 4" x 4" redwood 2.8 below ground. Set 60d nail in center, placed 1" O.D. pipe over nail in center of redwood with plug L.S. 4156 at 0.20 below groundline.

PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

SET 1" O.D. x 28" GALVANIZED IRON PIPE TAGGED L.S. 4156 @ 0.2 ft. BELOW GROUND LINE OVER 4" x 4" REDWOOD.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION STATION
ZONE ELEVATION NORTHINGS (Y) EASTINGS (X)

SKETCH: (Include reference tie or witness points, remarks and topo of area)

276.14 Southeast from nail & shiner in power pole
196.36 Northwest from nail & shiner in northside of power pole
32.05 Northeast from "X" on south side of 30" standpipe



SURVEYOR'S CERTIFICATE
THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON Feb 25 1980

COUNTY SURVEYOR'S CERTIFICATE
THE CORNER RECORD WAS RECEIVED Feb 25 1980 AND EXAMINED AND FILED BY: Wall Mitchell

SEAL

DOCUMENT No. 3120

STATEMENT ON BACK OF SHEET

YES [] NO []