


NO. 3125-K

CORNER RECORD

COUNTY OF Merced T. 9S R. 15E M.D.B. MERIDIAN CALIFORNIA

CORNER TYPE: GOV'T. CORNER [] MEANDER [] RANCHO [] CONTROL [] OTHER []
CORNER IDENTIFICATION — DATE OF VISIT June 3, 1977



Northwest corner of Lot 15, Block 21, (Section 21) as shown on the Map of the Bliss Ranch Subdivision on file in Volume 7 of plats at page 46, M.C.R.

CORNER — LEFT AS FOUND [] FOUND AND TAGGED [] REESTABLISHED OBLITERATED CORNER [] REBUILT [x]

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Set 1" O.D. x 28" galvanized pipe with plastic plug marked L.S. 4156 at 0.5 below groundline AT PROPORTIONAL DISTANCE BETWEEN THE N.W. COR. LOT 2 AND THE N.E. COR. OF LOT 16.

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST [] SECOND [] THIRD []
STATIONS USED: NGS (USC & GS) [] STATE [] COUNTY [] OTHER [] STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

37.78 South from nail & shiner in 6" diameter grape brace post
33.87 East from nail & shiner in railroad tie post
25.75 Northwest of scribed "X" in inlet of concrete structure
51.31 Northwest of scribed "X" in outlet of concrete structure



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON 15.4156 Feb. 29 1980

SIGNED

Johnny E. Davis
4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED Feb. 25 1980 AND EXAMINED AND FILED 19

BY: *Walter Mitchell*

TITLE:

DOCUMENT No. 3125-K

STATEMENT ON BACK OF SHEET

YES [] NO []