

3394

CORNER RECORD

COUNTY OF Merced T. 9 S. R. 14 E. Mt. Diablo MERIDIAN CALIFORNIA

CORNER TYPE: GOVT. CORNER MEANDER RANCHO CONTROL OTHER

CORNER IDENTIFICATION — DATE OF VISIT December 6, 1976



Northwest Corner Lot 20, Block 24 (Section 24) as shown on Map of the Bliss Ranch Subdivision on file in Volume 7 of plats at page 44, M.C.R.

CORNER — LEFT AS FOUND FOUND AND TAGGED REESTABLISHED OBLITERATED CORNER REBUILT

PHYSICAL DESCRIPTION OF CORNER FOUND; EVIDENCE AND METHOD USED TO IDENTIFY OR REESTABLISH

Found 4" x 4" redwood post 1.5 below ground


PHYSICAL DESCRIPTION OF MONUMENTS REBUILT OR PERPETUATED

Found 4" x 4" redwood set in center 1" O.D. pipe plugges L.S. 4156 0.9 below ground line

CALIFORNIA COORDINATE SYSTEM ORDER: FIRST SECOND THIRD
STATIONS USED: NGS (USC & GS) STATE COUNTY OTHER STATION _____ STATION _____
ZONE _____ ELEVATION _____ NORTHINGS (Y) _____ EASTINGS (X) _____

SKETCH: (Include reference tie or witness points, remarks and topo of area)

- 82.05 South from nail & shiner in power pole.
- 53.90 West from nail & shiner in railroad tie.
- 15.44 East from nail & shiner in railroad tie.
- 1.97 East from nail & shiner in railroad tie.



SURVEYOR'S CERTIFICATE

THIS CORNER RECORD WAS PREPARED BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE LAND SURVEYORS ACT ON L.S. 4156 January 31, 1979

SIGNED: *Johnny E. Davis*

L.S. or R.C.E. No.: 4156

SEAL

COUNTY SURVEYOR'S CERTIFICATE

THE CORNER RECORD WAS RECEIVED _____ 19____ AND EXAMINED AND FILED _____ 19____

BY: _____

TITLE: _____

DOCUMENT No. 3394

STATEMENT ON BACK OF SHEET

YES NO